UNCLASSIFIED	
AD NUMBER: AD08	81061
LIMITATION CHAN	GES
TO:	
Approved for public release; distribution is un	limited.
FROM:	
Distribution authorized to U.S. Gov't. agencies Export Control, 1 Oct 1970. Other requests sha Systems Command, AIR-536B2, Washington, E	all be referred to the Naval Air
AUTHORITY	
USNASC LTR, 10 NOV 1976	
OSNASCETT, TO NOV 1570	

THIS REPORT HAS BEEN DELIMITED AND CLEARED FOR PUBLIC RELEADE UNDER DOB DIRECTIVE 5200,20 AND NO RESTRICTIONS ARE IMPOSED UPON ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIAITED.

EVALUATION OF ADVANCED GEAR MATERIALS FOR GEAR BOXES AND TRANSMISSIONS



Final Report

(29 August 1968 to 28 October 1970)

October 1970

by J. P. Alberti A. J. Lemanski

Prepared Under Contract N00156-69-C-0634

for

Naval Air Propulsion Test Center

Department of the Navy

This document is subject to special export controls, and each transmittal to foreign governments or foreign nationals may be made only with prior approval of Naval Air Systems Command (AIR 536B2).

Wash DC 20360

The Boeing Company, Vertol Division Boeing Center, P. O. Box 16858

Philadelphia, Penna. 19142




SUMMARY

The purpose of this project was to investigate the surface load carrying capability of one candidate advanced gear material by carrying out a program of experimental investigation to assess its resistance to surface fatigue (pitting and spalling).

This report presents the results of an experimental test program for evaluating the surface load capacity of VASCO-X2 (.24 carbon) high hot hardness tool steel spur gears and baseline spur gears fabricated from the currently used AISI 9310 (AMS 6260) aircraft gear steel.

The test program consisted of conducting rotating load tests on gear specimens of 5.333 diametral pitch, 4.50 and 7.50-inches pinion and gear pitch diameters respectively, 0.5-inch face width, form ground full circular fillets, case carburized, and heat treated to aircraft quality standards. The tooth geometry was designed to achieve pitting and spalling as the predominate failure mode under overload conditions. Ten test data points were achieved for each of the two materials under evaluation.

A summary of the mean endurance limits derived from the test data points for both materials is shown in the figure below:



Summary of Mean Endurance Limits
Derived from Test Data Points.

The conclusions of this report are summarized as follows:

- 1. The test results obtained on the VASCO-X2 (.24 carbon) high hot hardness tool steel gears revealed that this material demonstrated a capability of carrying at least 30 percent more load than gears fabricated from AISI 9310 (AMS 6260) case carburized steel.
- 2. It is believed that the load carrying capacity of the VASCO-X2 gears may have been affected by the high percentage of retained austenite and heavy carbide network disclosed by the destructive metallurgical examination.
- 3. An analysis of the ten VASCO-X2 data points and the ten AISI 9310 data points revealed that both materials exhibited a very small degree of scatter, thereby indicating a high degree of repeatability.

FOREWORD

This report presents an evaluation and the results of an experimental program for the investigation of the surface fatigue load capacity of one candidate advanced gear material and one of the current aircraft gear steels. The evaluation was accomplished by conducting rotating load testing of typically sized aircraft quality spur gears manufactured from the two materials. The program was conducted during the period from 24 June 1969 to 28 October 1970 for the U. S. Naval Air Propulsion Test Center, Philadelphia, Pennsylvania under Contract N00156-69-C-0634 (Mod P002).

Technical direction was provided by Mr. James Conboy, Aerospace Engineer of the Naval Air Propulsion Test Center.

The program was conducted at the Vertol Division of the Boeing Company, under the technical supervision of A. J. Lemanski, Chief Advanced Drive System Technology Department. Principal investigators for the program were J. P. Alberti, Project Engineer and V. J. Perillo. Data analysis was accomplished by H. J. Rose.

Acknowledgement is made to Professor W. J. Murphy and his staff at Villanova University for their contributions and assistance during the experimental test program phase.

TABLE OF CONTENTS

Sec	<u>etion</u>	<u>Paqe</u>
SUM	MARY	iii
FOR	REWORD	V
LIS	T OF ILLUSTRATIONS	vii
LIS	T OF TABLES	12
1.	INTRODUCTION	1
2.	TECHNICAL APPROACH	3
	Background	3
3.	TEST METHOD	5
	Test Specimen Design Material Specimen Fabrication Metallurgical Evaluation Test Apparatus Testing Technique Gear Stress Calculations	5 15 15 18 18 18 25
4.	TEST RESULTS	29 29 29 45
5.	CONCLUSIONS	53
6.	RECOMMENDATIONS	55
7.	REFERENCES AND BIBLIOGRAPHY	57

LIST OF ILLUSTRATIONS

<u>Figure</u>		Page
	Summary of Mean Endurance Limits	iii
1	AISI 9310 Steel Test Gear for Rotating Fatigue Test (SK21984, 1.67 Gear Ratio, 5.33 Diametral Pitch)	• 7
2	AISI 9310 Steel Test Pinion for Rotating Fatigue Test (SK21985, 1.67 Gear Ratio, 5.33 Diametral Pitch)	9
3	VASCO-X2 Test Gear for Rotating Fatigue Test (SK21988, 1.67 Gear Ratio, 5.33 Diametral Pitch)	. 11
4	VASCO-X2 Test Pinion for Rotating Fatigue Test (SK21989, 1.67 Gear Ratio, 5.33 Diametral Pitch)	. 13
5	Tooth No. 4 of AISI 9310 Steel Test Pinion (SK21985, Serial No. 5, As Received)	16
6	Tooth No. 8 of AISI 9310 Steel Test Gear (SK2198 Serial No. 1, As Received)	34, 16
7	Tooth No. 24 of VASCO-X2 Steel Test Gear (SK21988, Serial No. 1, Side A, As Received)	. 17
8	Tooth No. 5 of VASCO-X2 Steel Test Pinion (SK21989, Serial No. 1, Side B, As Received)	. 17
9	Gear Research Test Stand	20
10	Research Test Stand Overhung Configuration	. 21
11	Deadweight Torsion Test Machine	23
12	Test Box Vibration Signatures for SK21988 (Serial No. 1, Side B) and SK21989 (Serial No. 1 at Scale of 0.05 Volta per Continutor	.)

<u>Figure</u>		Page
13	Test Gear Bending Stress (SK21984, SK21985, SK21988, and SK21989)	26
14	Test Gear Pitch Line Contact Stress (SK21984, SK21985, SK21988, and SK21989)	2 8
15	Final Condition of AISI 9310 Steel Test Pinion (SK21985, Serial No. 2)	36
16	Final Condition of AISI 9310 Steel Test Pinion (SK21985, Serial No. 3)	37
17	Final Condition of AISI 9310 Steel Test Pinion (SK21985, Serial No. 5)	38
18	Final Condition of AISI 9310 Steel Test Pinion (SK21985, Serial No. 4)	39
19	Final Condition of AISO 9310 Steel Test Pinion (SK21985, Serial No. 1)	40
20	Final Condition of VASCO-X2 Steel Test Pinion (SK21985, Serial No. 4)	41
21	Final Condition of VASCO-X2 Steel Test Pinion (SK21989, Serial No. 3)	42
22	Final Condition of VASCO-X2 Steel Test Pinion (SK21989, Serial No. 2)	43
23	Final Condition of VASCO-X2 Steel Test Pinion (SK21989, Serial No. 5)	44
24	Contact Burn on AISI 9310 Steel Pinion	46
25	Surface Durability Life Factor (AGMA Standard 210.02)	49
26	Test Data Points with Mean Endurance Limits at 99 Percent Confidence Level	50
27	Mean Endurance Limits for a 99.5 Percent Probability of Survival	52

LIST OF TABLES

<u>Table</u>		<u>Page</u>
1	Test Specimen General Design Parameters	. 6
2	Specified Chemical Composition (Percentage by Weight)	. 19
3	Actual Test Specimen Metallurgical Analysis (One Sample of Each Material)	. 19
4	Load Schedule for Baseline AISI 9310 Steel Gears	. 30
5	Load Schedule for VASCO-X2 Steel Gears	. 30
6	Summary of Test Results for AISI 9310 Steel Test Gears (Spur)	. 31
7	Summary of Test Results for VASCO-X2 Steel Test Gears	. 33
8	Results of Statistical Analysis	. 47
9	Test Data and Calculated Endurance Limits .	. 48

1. INTRODUCTION

The objective of this project was to investigate the surface load carrying capability of spur test gear specimens fabricated from VASCO-X2 case carburized high hot hardness tool steel as compared to current aircraft baseline test gears fabricated from AISI 9310 steel.

During the past decade, a significant problem in helicopter transmission gearing has been the incidence of pitting failures. Considerable effort has been expended by the aircraft industry in an attempt to find a consistent solution to this problem. To date, these efforts have not provided the desired results.

Elements such as gear teeth which roll and slide against each other under high contact pressures are subjected to the development of surface pits or spalls after many repetitions of load. This pitting is generally understood as a manifestation of metal fatigue due to the imposed cyclic contact stresses.

It is also becoming recognized that one of the principal modes of contact fatigue is initiated by surface distress due to thin oil films, and the majority of slow speed gear drives are operating with only partial elastohydrodynamic separation. Distress of this type is likely to be strongly affected by the interacting chemistry of the steel and fluid.

Steel composition alone is not thought to have a significant effect on pitting fatigue, except insofar as it influences hardenability and microstructure. On the other hand, interactions between different steels or microstructures and lubricants do seem to influence fatigue behavior.

2. TECHNICAL APPROACH

Background

Boeing's Vertol Division has long recognized the need for a more reliable gear material for helicopter transmissions. In 1966 a company-sponsored independent research program was initiated to explore improved materials with a potential of increased load carrying capacity over current gear materials. The initial program was exploratory in nature and consisted of a screening evaluation of several tool steels, nitralloy steels, and carburizing steels. From this work, the VASCO-X2 high hot hardness tool steel was selected for further evaluation.

A follow-on company-sponsored screening program was initiated in 1967 to evaluate the relative surface load carrying capacity of VASCO-X2 (.24 carbon) case carburized steel. The test specimens were spur gears of 5 diametral pitch, 0.50-inch face width and 6.00-inches pitch diameter fabricated to aircraft quality standards. This gear test program revealed the following:

- 1. The rotating surface fatigue evaluation testing of the VASCO-X2 (.24 carbon) test gears demonstrated the capability of successfully carrying 2.40 times the design load for 10 million cycles without evidence of pitting or spalling. The Hertz contact stress at this load level was 216,000 psi in comparison to 150,000 psi for the design load.
- 2. There was evidence that the VASCO-X2 test gears developed a protective surface layer on the working tooth surface under the operating loads. The protective layer was evident after an initial period of operation.

Statement of Problem

Current helicopter transmission power gears are limited in load carrying capacity because current materials do not resist surface damage in the form of pitting and spalling failures. However, the bending strength and flexural fatigue resistance of these materials has not imposed design limitations of the same order. In the case of bending stress index allowables, the designer appears to have a considerably greater margin in which to work.

The primary concern of the transmission gear design engineer is in providing adequate tooth strength. For this reason, gear materials are selected mainly for beam strength. To improve the sliding behavior of the material, the usual procedure is to then harden the surfaces. Due to the emphasis on the development of gear materials for strength rather than for good sliding characteristics, most aircraft gears will pit or spall under conditions which are far less severe than those which would cause tooth breakage, particularly at low speeds. In many aircraft gear applications, pitting is a limiting factor in reducing the size and weight of transmissions.

Requirements for the next generation of helicopter and V/STOL transmission designs are placing stringent demands on power gear materials. It has become increasingly obvious that substantial improvements in load capacity and performance cannot be expected from current gear materials. Therefore, aircraft performance will be penalized by reductions in payload because of the increased transmission weights necessary to meet the performance objectives of increased reliability and maintainability.

This problem may be overcome by the use of advanced gear materials that provide greater resistance to surface fatigue failures than present materials, and do not compromise resistance to flexural fatigue failures.

3. TEST METHOD

Test Specimen Design

The design of the test gears used in this program was within the experience range of helicopter main transmission power gears in pitch diameter, diametral pitch, pressure angle and profile modification. Processing procedures, tolerance parameters, and record requirements conformed to the appropriate Boeing-Vertol production specifications. The test gear design parameters were carefully selected to increase the probability of producing pitting failures, while reducing the probability of experiencing scoring (scuffing) and/or bending failures.

With this objective in mind, and to determine the surface load capacity of the two materials under investigation on a comparative basis, the test gears for this program were designed with the following specific parameters. The gear ratio (Mg) of 1.67 to 1.00 was selected as the most practical for a 6.00-inch center distance while maintaining a reasonable bolt circle for mounting purposes. The roll angle to the first point of contact on the pinion member was maintained below 7 degrees. The pinion member was designed with a short addendum (0.06-inch) and the gear member with a long addendum (0.22-inch). The resulting profile contact ratio was 1.13 minimum, which is below normal design practice. Pinion input speed was selected as 910 rom.

Kinematic analysis of the design parameters, using an existing Boeing-Vertol computer program, indicated a very high specific sliding (slide/roll ratio) value at the first point of contact on the pinion member. The specific sliding value at this point was considerably higher than the value for any other point along the tooth profile, indicating a high probability of experiencing surface type failures in the pinion dedendum.

Each group of test gears (for each of the two materials) was fabricated from one heat and melt of material, and heat treated in one lot (except for one gear member for the VASCO-X2 steel) to minimize possible processing variations. Eleven test gears were manufactured from the AISI 9310 steel and ten gears were manufactured from the VASCO-X2 (.24 carbon) steel in accordance with the drawing specifications shown in Figures 1, 2, 3, and 4. The general design parameters are listed in Table 1.

The final design parameters selected for the gear test specimens were specifically chosen to increase the pitting probability; consequently, they are not representative of typical aircraft design practice.

TABLE 1. TEST SPECIMEN GENERAL DESIGN PARAMETERS

Drawing Number	Description	Material (Steel)	Pitch Diameter (inches)	Diametral Pitch	Gear	Pressure Angle (degrees)	Face Width (inches)
SK21984	Gear	AISI 9310	7.500	5.333	1.67	20	0.500
SK21985	Pinion	AISI 9310	4.500	5.333	1.67	20	0.500
SK21988	Gear	VASCO-X2	7.500	5.333	1.67	20	0.500
SK21989	Pinion	VASCO-X2	4.500	5.333	1.67	20	0.500

		1
2105	MAX	NUM
3087	MIN	DIAN
012	MAX	PRES
008	MIN	PITC
70476	952	OUT
ACE WI	DTH	ROO
		FOR
		MEA
E		FULL
		PIN
		-
7		
	3087 012 008 7.0476 ACE WI	3087 MIN 012 MAX 008 MIN 7.0476952 ACE WIDTH 01 RH 01 LH E




Figure 1. AISI 9310 Steel Test Gear for Rotating Fatigue Test (SK21984, 1.67 Gear Ratio, 5.33 Diametral Pitch)

10	EXTERNAL SPUR GEAR C	IATA
T 3105 MAX	NUMBER OF TEETH	40
5087 MIN	DIAMETRAL PITCH	5 3333
ON DIE MAX	PRESSURE ANGLE	20
UOS MIN	PITCH DIAMETER @-AOOI T.LR.	7 500
7 2476952	OUTSIDE DIAMETER	8 000 : 223
F FALE WIDTH	ROOT DIAMETER	7 213 : 100
0001 RH	FORM DIAMETER	7 3861
0001 LH	MEASUREMENT OVER TWO PINS	8.1586 MAX
NEF.	FULL FILLET RADIUS (REF)	126
0006	PIN DIAMETER	.3840
65 (-0005)(-0008)	SIDE A SIDE B DIMENSIONS SAME AS SIDE A	LEANCE SIOL B
.85° (.0000)(0002) -97° (-0003)(0008)	72.	

E # 7 5 8 14 1 6 8 10 2 5 5 4 8 18 1


NOTES

- ALL DIAMETERS ON A COMMON CENTERLINE TO BE CONCENTRIC TO EACH OTHER WITHIN .OID TIR. UNLESS OTHERWISE NOTED.
- 2 MAXIMUM SURFACE ROUGHNESS 125 EXCEPT AS NOTED.
- RELATIVE AZIMUTH POSITION OF GEAR TEETH AND HOLES OPTIONAL UNLESS SPECIFIED.
- BARAN ALL SHARP EDGES NOT SPECIFIED TO A RADIUS OR CHAMPER OF .010 TO .020
- 5 NITAL ETCH INSPECTION PER BORING PROCESS SPECIFICATION BAC 5436.
- FLUORESCENT MAGNETIC PARTICLE INSPECTION PER BOEING PROCESS SPECIFICATION BAC 5424 CLASS A.

 7 FINISH ON GEAR TEETH FLANKS 3 MAXIMUM BOTH SIDES.
- (B) MARK PART AND SERIAL NUMBER HERE. VIBRO ETCH PER BOEING PROCESS SPECIFICATION BAC 5307 TYPE'VE'. DO NOT IMPRESSION STAMP.
- 1 LEAD TOLERANCE APPLIES TO FULL FACE WIDTH MINUS EDGE BREAKS. CROWNING OR END RELIEF TO BE AVOIDED.
- 10 BILLET OR BAR SHALL HAVE A MINIMUM MECHANICAL REDUCTION OF 3 TO 1 FROM THE INSOT.
- II. CARBURIZED TEST SAMPLES SHALL BE FACSIMILES OF GEAR TEETH.
- 12 QUALITY CONTROL PER BORING SPECIFICATION MS 14.02
- PROFILE SHAPE WITHIN THE TOLERANCE BAND SHALL BE A SMOOTH AND GRADUAL CONVEX CURVATURE. NO STEPS OR GROOVES PERMITTED.
- THE FULL CIRCULAR FILLET SHALL BE A SMOOTH CURVATURE WITH NO STEPS OR GROOVES.
- 13 THE TOOTH PROFILES AND FILLETS SHALL BE FINISH MACHINED BY FORM GRINDING WITH NO UNDERCUT PERMITTED.
- TE BREAK ALL EDGES OF GEAR TEETH . OOS TO . OIS WITH TAMPICO BRUSH.
- HEAT TREATMENT
 A. CARBURIZE ENCLOSED AREAS PER BOLING PROCESS
 - A. CARBURIZE ENCLOSED AREAS PER BOEING PROCESS
 SPECIFICATION MS 12.02

 B. CARBURIZED CASE HARDNESS ROCKWELL C
 C. EFFECTIVE CASE DEPTH AFTER GRINDING
 D. CORE HARDNESS ROCKWELL C
 E. CORE STRENGTH RS.I. (REF)
 F. DRAW AT 300'F TO 32S'F FOR FOUR HOURS AFTER FINAL GRIND. AREA A AREA B 60-64 030-045 36-40

HEFERENCE DATA	
CIRCULAR TOOTH THICKNESS AT	.2702 MAX
PITCH DIAMETER	.2683 MIN
BACKLASH WITH MATING GEAR ON	.012 MAX
STANDARD CENTERS	NIM 800.
BASE CIRCLE DIAMETER (REF)	4.2286167
3 LEAD TOLERANCE PER INCH	OF WIDTH
	0001 RH
TOTAL INDEX TOLER	ANCE
A .0006	8 .0006
PITCH TOLERANCE	
A .0002	B .0002



OUTSIDE DIAMETER 25.05' (-0007/(-0010) —


PITCH DIAMETER 20.85' (0000/(-0002) —

CONTROL POINT NO 1 19.76' (0000/(-0001) —

CONTROL POINT NO 2 10.76' (.0000/(-0001) —

FORM DIAMETER 1.76' (-.0006/(-0009) —

Figure 2. AISI 9310 Steel Test Pinion for Rotating Fatigue Test (SK21985, 1.67 Gear Ratio, 5.33 Diametral Pitch)



NOTES

- ALL DIAMETERS ON A COMMON CENTENLINE TO BE CONCENTRIC TO EACH OTHER WITHIN . GIO T.I.R. UNLESS OTHERWISE
- MAXIMUM SURFACE ROUGHNESS EXCEPT AS NOTED.
- RELATIVE AZIMUTH POSITION OF GEAR TEETH AND HOLES OPTIONAL UNLESS SPECIFIED.
- BREAK ALL SHARP EDGES NOT SPECIFIED TO A RADIUS OR CHAMFER OF .010 TO .020
- NITAL ETCH INSPECTION PER BOEING PROCESS SPECIFICATION BAC 5436.
- 6.> FLUDRESCENT MAGNETIC FARTICLE INSPECTION PER BOEING PROCESS SPECIFICATION BAC 5424 CLASS A.
- FINISH ON GEAR TEETH FLANKS V MAXIMUM BOTH SIDES.
- MARK PART AND SERIAL NUMBER HERE. VIBRO ETCH PER BORING PROCESS SPECIFICATION BAC 5307 TYPE 'VE' DO NOT IMPRESSION STAMP.
- LEAD TOLERANCE APPLIED TO FULL FACE WIDTH MINUS EDGE BREAKS.
- 10. BILLET OR BAR SHALL HAVE A MINIMUM MECHANICAL REDUCTION OF 3 TO 1 FROM THE INGOT.
- II. CARBURIZED TEST SAMPLES SHALL BE FACSIMILES OF GEAR TEETH.
- IZ. QUALITY CONTROL PER BOEING SPECIFICATION MS 14.02
- PROFILE SHAPE WITHIN THE TOLERANCE BAND SHALL BE A SMOOTH AND GRADUAL CONVEX CURVATURE. NO STEPS OR GROOVES PERMITTED.
- THE FULL CIRCULAR FILLET SHALL BE A SMOOTH CURVATURE WITH NO STEPS OR GROOVES.
- THE TOOTH PROFILES AND FILLETS SHALL BE FINISH MACHINED BY FORM GRINDING WITH NO UNDERCUT PERMITTED.
- BREAK ALL EDGES OF GEAR TEETH . OOS TO . OIS WITH TAMPICO BRUSH.
- TE HEAT TREATMENT

 A. CARBURIZE ENCLOSED AREA PER BOEING PROCESS
 - AREA A AREA B SPECIFICATION MS 12.02

 B. CARBURIZED CASE HARDNESS ROCKWELL C. .030 -.045 36 - 40 C. EFFECTIVE CASE DEPTH AFTER GRINDING
 D. CORE HARDNESS ROCKWELL C
 E. CORE STRENGTH PSI (REF) 160,000 181,000 F. DRAW AT 300°F - 325°F FOR FOUR HOURS AFTER FINAL GRIND.

REFERENCE DATA			İ
CIRCULAR TOOTH THICKNESS AT PITCH DIAMETER	.3105	MAX	NUMB
BACKLASH WITH MATING GEAR ON STANDARD CENTERS BASE CIRCLE DIAMETER (REF)	012	MAX	PITCH
S LEAD TOLERANCE PER INCH OF F	ACE WI		ROOT
TOTAL INDEX TOLERANC	E E	LH	MEAS
PITCH TOLENANCE			PIN D

30.65 (-.0005)(-.0008)

OUTSIDE DIAMETER





Figure 3. VASCO-X2 Test Gear for Rotating Fatigue Test (SK21988, (SK21988, 1.67 Gear Ratio, 5.33 Diametral Pitch)



]a

NOTES

- ALL DIAMETERS ON A COMMON CENTERLINE TO BE CONCENTRIC TO EACH OTHER WITHIN DIO TIR. UNLESS OTHERWISE NOTED.
- 2 MAXIMUM SURFACE ROUGHNESS IZE EXCEPT AS NOTED.
- RELATIVE AZIMALTH POSITION OF GEAR TEETH AND HOLES OPTIONAL BULESS SPECIFIED
- BREAK ALL SHARP EDGES NOT SPECIFIED TO A RADIUS OR CHAMFER OF .010 TO .020
- NITAL ETCH INSPECTION PER BORING PROCESS SPECIFICATION BAC 5436.
- FLUORESCENT MAGNETIC PARTICLE INSPECTION PER BOEING PROCESS SPECIFICATION BAC 5424 CLASS A.

 7 FINISH ON GEAR TEETH FLANKS 34 MAXIMUM BOTH SIDES.
- BO MARK PART AND SERIAL NUMBER HERE. VIBRO ETCH PER BOEING PROCESS SPECIFICATION BAC 5307 TYPE'VE'. DO NOT IMPRESSION STAMP.
- 1 LEAD TOLERANCE APPLIES TO FULL FACE WIDTH MINUS EDGE BREAKS. CROWNING OR END RELIEF TO BE AVOIDED.
- 10 BILLET OR BAR SHALL HAVE A MINIMUM MECHANICAL REDUCTION OF 3 TO 1 FROM THE INSOT.
- H. CARBURIZED TEST SAMPLES SHALL BE FACSIMILES OF GEAR TEETH.
- 12 QUALITY CONTROL PER BORING SPECIFICATION MS 14.02
- PROFILE SHAPE WITHIN THE TOLERANCE BAND SHALL BE A SMOOTH AND GRADUAL CONVEX CURVATURE. NO STEPS OR GROOVES PERMITTED.
- THE FULL CIRCULAR FILLET SHALL BE A SMOOTH CURVATURE WITH NO STEPS OR GROOVES.
- 15 THE TOOTH PROFILES AND FILLETS SHALL BE FINISH MACHINED BY FORM GRINDING WITH NO UNDERCUT PERMITTED.
- BREAK ALL EDGES OF GEAR TEETH . OOS TO DIS WITH TAMPICO BRUSH.
- TT PURCHASE MATERIAL FROM :-
 - VANADIUM ALLOYS STEEL COMPANY LATROBE, PENNSYLVANIA VASCO LOW CARBON HOT FORM. APPROXIMATE ANALYS
 - APPROXIMATE ANALYSIS: FORM. APPROX
 SULPHUR .007
 PHOSPHDRUS .005
 CHROMIUM 4700 83 CARBON MOLYBOENUM
 - MANGANESE .30
- TE HEAT TREATMENT
 - 1. ANNEAL
 - A 1600-1650'F ONE HOUR
 - B. COOL TO BOO'F AT SO DEGREES F PER HOUR.
 C. AIR COOL TO ROOM TEMPERATURE.
 - 2. ROUGH MACHINE.

 - 2. ROUGH MACHINE.

 3 STABILIZE HEAT TREAT.

 A. COPPER PLATE TO BAC 5722 AND PREHEAT 1+00'F IN PROTECTIVE ATMOSPHERE.

 B. HARDEN 1850'F IN PROTECTIVE ATMOSPHERE.

 C. AIR QUENCH TO ROOM TEMPERATURE.

 D. DOUBLE TEMPER 2-+ HOURS AT 1200'F FOR ROCKWELL 36 NOMINAL.

 4. FINISH MACHINE EXCEPT FINAL GRIND.


 5. CARBURGETS:

 - S. CARBURIZE:

 - URIZE.
 A. ALUMINUM OXIDE CLEAN.
 B. PREMEAT 1750'F ONE HOUR.
 C. CARBURIZE AT 1750'F WITH .50-.55 PERCENT CARBON CONTENT IN OUTER .OOS OF CASE TO ACHIEVE AN EFFECTIVE CASE DEPTH (ROCKWELL CSO) AFTER GRINDING .O30-.O45 INCHES.(REF NOTE 18.7)
 - D STILL AIR QUENCH TO IZS-150°F.
 E DOUBLE TEMPER 950°F 2-4 HOURS.
 G. FINISH GRIND AS REQUIRED.

 - CORE HARDNESS ROCKWELL C - 50 MAX
 - 8 ALL CARBURIZING AND HEAT TREATMENT EQUIPMENT SHALL CONFORM TO MIL-H-6875.

REFERENCE DATA		
CIRCULAR TOOTH THICKNESS AT	.270	XAM SC
PITCH DIAMETER	.266	33 MIN
BACKLASH WITH MATING GEAR ON	.012	MAX
STANDARD CENTERS	.00	MIN E
BASE CIRCLE DIAMETER (REF)	_	86167
3 LEAD TOLERANCE PER INCH	OF I	WIDTH
		RH
	801	LH
TOTAL INDEX TOLERA	NCE	
A .0006		0006
PITCH TOLERANCE	_=	
A .0002	8.	000z



OUTSIDE DIAMETER 25 US (-.0007)(-.0010)


PITCH DIAMETER. 20.85 (-.0000)(-.0002)

CONTROL POINT NO 1 19.76 (.0000)(-.0001)

CONTROL POINT NO 2 10.76 (.0000)(-.0001)

FORM DIAMETER 1.76 (.0006)(-.0009)

Figure 4. VASCO-X2 Test Pinion for Rotating Fatigue Test (SK21989, 1.67 Gear Ratio, 5.33 Diametral Pitch)



NOTES

- ALL DIAMETERS ON A COMMON CENTENLINE TO BE CONCENTRIC TO EACH OTHER WITHIN .OID T.I.R. UNLESS OTHERWISE
- MAXIMUM SURFACE ROUGHNESS " EXCEPT AS NOTED.
- RELATIVE AZIMUTH POSITION OF GEAR TEETH AND HOLES OPTIONAL UNLESS SPECIFIED.
- BREAK ALL SHARP EDGES NOT SPECIFIED TO A RADIUS OR CHAMFER OF .GIO TO .020
- NITAL ETCH INSPECTION PER BOEING PROCESS SPECIFICATION BAC 5436
- 6. FLUORESCENT MAGNETIC PARTICLE INSPECTION PER BOEING PROCESS SPECIFICATION BAC 5424 CLASS A.
- FINISH ON GEAR TEETH FLANKS & MAXIMUM BOTH SIDES.
- B. MARK PART AND SERIAL NUMBER HERE. VIBRO ETCH PER BOEING PROCESS SPECIFICATION BAC 5307 TYPE 'VE'. DO NOT IMPRESSION STAMP.
- 19. LEAD TOLERANCE APPLIED TO FULL FACE WIDTH MINUS EDGE BREAKS.
- 10. BILLET OR BAR SHALL HAVE A MINIMUM MECHANICAL REDUCTION OF 3 TO 1 FROM THE INGOT.
- CARBURIZED TEST SAMPLES SHALL BE FACSIMILES OF GEAR TEETH.
- 12. QUALITY CONTROL PER BOEING SPECIFICATION MS 14.02
- PROFILE SHAPE WITHIN THE TOLERANCE BAND SHALL BE A SMOOTH AND GRADUAL CONVEX CURVATURE. NO STEPS OR GROOVES PERMITTED.
- THE FULL CIRCULAR FILLET SHALL BE A SMOOTH CURVATURE WITH NO STEPS OR GROOVES.
- THE TOOTH PROFILES AND FILLETS SHALL BE FINISH MACHINED BY FORM GRINDING WITH NO UNDERCUT PERMITTED.
- PURCHASE MATERIAL FROM:
 VANADIUM ALLOYS STEEL COMPANY, LATROBE, PENNSYLVANIA. VASCO LOW CARBON HOT FORM. APPROXIMATE ANALYSIS:

SUL PHUR PHOSPHORUS 24 .007 MOLYBOENUM 1.32 .47 SILICON .63 VANADIUM TUNGSTEN .009 MANGANESE .30 CHROMIUM

- HEAT TREATMENT
 - 1. ANNEAL

 - A. 1600 1650F ONE HOUR B. COOL TO BOO'F AT 50 DEGREES F PER HOUR C. AIR COOL TO ROOM TEMPERATURE
 - 3. STABILIZE HEAT TREAT
 - A. COPPER PLATE TO BAC 5722 AND PREHEAT MOO'F IN PROTECTIVE ATMOSPHERE.
 - B. HARDEN 1850'F IN PROTECTIVE ATMOSPHERE.
 C. AIR QUENCH TO ROOM TEMPERATURE.

 - D. DOUBLE TEMPER 2-4 HOURS AT 1200'F FOR ROCKWELL 36 NOMINAL.
 - 4. FINISH MACHINE EXCEPT FINAL GRIND.
 - 5. CARBURIZE:
 - A. ALUMINUM OXIDE CLEAN.
 - B. PREHEAT 1750"F ONE HOUR.
 - C. CARBURIZE AT 1750'F WITH .90 -. B5 PERCENT CARBON CONTENT IN OUTER . OOS OF CASE TO ACHIEVE AN EFFECTIVE CASE DEPTH (ROCKWELL C 50) AFTER GRINDING . 030 -. 045 INCHES (REF. NOTE 17.7)
 - O. STALL AR QUENCH TO 125-150°F.
 E. DOUBLE TEMPER 950°F 2-4 MOURS.
 6. FINISH GRIND AS REQUIRED.

 - 7. CARBURIZE ENCLOSED AREA X CONTROL OF CARBURIZING PROCESS SHALL BE TO M.S. 12.02. CARBURIZED CASE HARDNESS ROCKWELL C-EFFECTIVE CASE DEPTH AFTER GRINDING --- 030 -- .045
- CORE HARDNESS ROCKWELL C ________ SO MAX

 8. ALL CARBURIZING AND HEAT TREATMENT EQUIPMENT SHALL CONFORM TO MIL-H-6875.
- BREAK ALL EDGES OF GEAR TEETH .005 TO .015 WITH TAMPICO BRUSH.



Material

The two materials selected for this investigation were AISI 9310 (AMS6260) steel and VASCO-X2 (.24 carbon) steel. These two materials are the same as the two candidate materials investigated under a previous contract, N00156-69-C-0634, Evaluation of Advanced Gear Materials for Gear Boxes and Transmissions. The previous program consisted of single-tooth nonrotating testing to evaluate the bending fatigue strength of these two materials. The current program was a logical follow-on to the original program to improve and extend the evaluation of these two materials - by evaluating the surface load carrying capacity through a rotating load test program.

Specimen Fabrication

The test gears for this program were fabricated by a vendor approved for the manufacture of helicopter gears, in accordance with the engineering drawings and the appropriate Boeing-Vertol specifications. The manufacturing procedure for all test gears was similar, and used the following basic processing sequence:

- 1. Forge material to individual biscuit.
- 2. Rough machine gear blank and stress relieve.
- 3. Final machine gear blank (bore, faces, outside diameter).
- 4. Machine gear teeth (hob).
- 5. Carburize gear teeth.
- 6. Heat treat (harden and draw).
- 7. Finish grind bore and end faces.
- 8. Grind gear teeth (form ground).
- 9. Bake.
- 10. Final inspection.

Figures 5 through 8 are photographs of the test gears in the as received condition.

Metallurgical Evaluation

A destructive metallurgical examination was conducted on SK21985, Serial No. 7, AISI 9310 (AMS6260) steel gear for determination of conformance to Boeing-Vertol specifications. The subject test gear conformed to all requirements and related specifications.




Figure 5. Tooth No. 4 of AISI 9310 Steel Test Pinion (SK21985, Serial No. 5, as received)




Figure 6. Tooth No. 8 of AISI 9310 Steel Test Gear (SK21984, Serial No. 1, as received)




Figure 7. Tooth No. 24 of VASCO-X2 Steel Test Gear (SK21988, Serial No. 1, Side A, as received)




Figure 8. Tooth No. 5 of VASCO-X2 Steel Test Pinion (SK21989, Serial No. 1, Side B, as received)

A destructive metallurgical examination was conducted on SK21989, Serial No. 1, VASCO-X2 steel gear, at the completion of testing, for determination of conformance to Boeing-Vertol specifications. Results of this investigation revealed that the core hardness was RC 53, which is over the requirement of RC 50 maximum. Microscopic examination revealed a heavy network of carbides to a depth of approximately 0.015 inch. This same zone was characterized by nearly circular zones of what appeared to be retained austenite. Microhardness results were above RC 60 at and close to the surface. The core microstructure was uniform tempered martensite. The amount of retained austenite was found to be variable, based on initial examination. Microscopic determinations were made and found to be approximately 30 percent; X-ray surface values were below 10 percent.

Table 2 contains a listing of the specified chemical analysis for the test gear materials and Table 3 lists the actual composition, hardness and cleanliness rating. Except for one gear member of the VASCO-X2 steel, all test gears of the same material were fabricated from the same heat and melt of steel to minimize possible variations which may be introduced by material processing.

Test Apparatus

The gear specimens were tested on a Boeing-Vertol regenerative (four square) load test stand (ST 0150). This test stand was specifically designed and constructed to conduct rotating load test programs for gear research and development. The test machine is capable of operation with three center distance options and provisions for control of torque, oil temperature and quantity of oil. Lubrication of all gear meshes and bearings is provided by individual oil jets (see Figure 9).

To facilitate short term operation and/or surface durability type testing, the design of this test stand includes the provision for testing outboard of the main gear housing, as shown in Figure 10. This feature provides for rapid assembly and disassembly of the test specimens, with improved accessibility for frequent visual inspection. This test stand configuration has a separate lubrication system with heating and cooling capabilities and direct oil flow measurement. Lubrication is directed to the test gears by individual externally cooled oil jets, which can be directed on the in-mesh side, out-of-mesh side, or both sides simultaneously. This configuration also permits control of oil flow rate, oil inlet temperature, and operating torque, while maintaining a constant speed.

Testing Technique


The primary test variables were shaft torque and oil inlet temperature. Gear tooth load was a function of shaft torque, which was applied through a lever system at the beginning of

TABLE 2. SPECIFIED CHEMICAL COMPOSITION (PERCENTAGE BY WEIGHT)

Element	Symbol	AISI 9310 (AMS6260)	VASCO-X2 (.24 Carbon)
Carbon Manganese Silicon Chromium Mclybdenum Vanadium Tungsten Nickel Sulphur Copper	C	0.07-0.13	0.20-0.25
	Mn	0.40-0.70	0.20-0.40
	Si	0.20-0.35	0.80-1.00
	Cr	1.00-1.40	4.75-5.25
	Mo	0.08-0.15	1.30-1.50
	V	-	0.40-0.50
	W	3.00-3.50	1.20-1.50
	Ni	0.025 Max	-
	S	0.35 Max	0.025 Max

TABLE 3. ACTUAL TEST SPECIMEN METALLURGICAL ANALYSIS (ONE SAMPLE OF EACH MATERIAL)

Specification	AISI 9310 (AMS6260) (%)	VASCO-X2 (.24 Carbon) (%)
Element Carbon Manganese Silicon	0.13 0.60 0.23	0.26 0.22 1.04
Chromium Molybdenum Vanadium Tungsten	1.28 0.11	5.30 1.28 0.44 1.25
Nickel Case Hardness, Rc Core Hardness, Rc Grain Size	2.99 60-61 39	- 60-62 53






Figure 9. Gear Research Test Stand




Figure 10. Research Test Stand Overhung Configuration

each test run. Torque levels were observed on an SR2 Strainsert instrument at specified intervals, and recorded. A final torque reading was taken and recorded at the conclusion of each test run. Deviation from the initial target torque was controlled to plus or minus 5 percent at startup and within plus or minus 2 percent during the individual test runs.

The torquemeter was calibrated prior to and at the completion of the test program. Calibration of the torquemeter was accomplished on a Riehle deadweight torsion test machine (Figure 11). Recalibration curves agreed within 2 percent with the initial calibration. Test time (cycles) was determined by a log record of running time and an elapsed time meter located in the test stand console. Power was supplied by an electric motor driving the input shaft through a toothed belt arrangement, maintaining the input pinion speed at 910 rpm.

Input oil temperature for the test gearbox was maintained at $135^{\circ}F \pm 5^{\circ}$ with input oil pressure of 55 psi \pm 5. The oil used for lubricating the test gearbox was MIL-L-23699A. Testing technique for this test program consisted of rotating load tests at each of the specified load levels for a maximum of 3 million cycles (or failure). Successful completion of a particular test run for 3 million cycles was considered as a test runout data point. This runout was then considered to be below the fatigue endurance limit. Prior to conducting the test runs the test gearbox oil sump was heated to raise the oil inlet temperature to 135 degrees \pm 5. The lubricating oil was circulated until the oil-temperature out gave indications of stabilizing. Jet lubrication was provided on the out-of-mesh side for the test gear mesh.

In addition to the visual inspections conducted at the specified intervals, constant surveillance of the test gearbox was provided through the use of accelerometers attached to the gear case. The vibration signatures were observed with an oscilloscope and the amplitudes were recorded in the test program log. Actual vibration signatures were photographed at specified intervals; Figure 12 is a typical example.

The test procedure for all test gears in this program was the same, and consisted of the following sequence.

- Conduct static pattern checks at the 50 percent and 100 percent load levels for load distribution evaluation.
- 2. Conduct a run-in rotating load test at the 50 percent load level for one hour (54,600 cycles).






Figure 11. Deadweight Torsion Test Machine



220 PERCENT LOAD, 8.46 X 10⁵ CYCLES



100 PERCENT LOAD, 9.09 X 10⁵ CYCLES

Figure 12. Test Box Vibration Signatures for SK21988 (Serial No. 1, Side B) and SK21989 (Serial No. 1) at Scale of 0.05 Volts per Centimeter.

3. Complete the test load schedule by conducting rotating tests for a maximum of 3 \times 106 cycles (or failure) at each of the specified load levels.

Gear Stress Calculations

The gear stress levels presented in this report were calculated by an existing Boeing-Vertol computer program which uses the following AGMA (American Gear Manufacturers Association) standards in the analysis:

- 220.02 Rating the strength of spur gear teeth
- 210.02 Surface durability of spur gears

AGMA 220.02 rates the bonding strength of spur gears as follows:

$$St = \frac{Wt.Ko}{Kt} \times \frac{Pd}{F} \times \frac{Ks.Km}{J}$$
 (1)

Where

Wt = transmitted tangential load (pounds)

Ko = overload factor

Kv = dynamic factor

Pd = diametral pitch

F = face width

Ks = size factor

Km = load distribution factor

J = geometry factor

For the test gears utilized in this program assume:

$$Ko, Kv, Ks, Km = 1.0$$
 (2)

then,

$$St = \frac{Wt \times 1}{1} \times \frac{5.333}{.500} \times \frac{1 \times 1}{.3808}$$
 (3)

$$St = 28.009 \times Wt \text{ (see Figure 13)}$$
 (4)

AGMA 210.01 rates the surface durability of spur gears as follows:

$$Sc = Cp \sqrt{\frac{Wt.Co}{cv} \frac{Cs}{d.F} \frac{Cm.Cf}{I}}$$
 (5)




Figure 13. Test Gear Bending Stress (SK21984, SK21985, SK21988, and SK21989)

where Sc = calculated contact stress number

Cp = elastic coefficient (2300 for steel gears)

Wt = transmitted tangential load at operating pitch

diameter (pounds)
Co = overload factor

Cv = dynamic factor

d = pinion operating pitch diameter (inches)
F = face width (inches)

Cs = size factor

Cm = load distribution factor

I = geometry factor

Cf = surface condition factor

For the test gears used in this program, assume:

Co, Cv, Cs, Cm, Cf =
$$1.0$$
 (6)

then,

Sc = 2300
$$\sqrt{\frac{\text{Wt x 1}}{1} \times \frac{1}{4.5 \times .50} \times \frac{1 \times 1}{.10}}$$
 (7)

$$Sc = 2300 \sqrt{\frac{Wt}{.225}} \text{ (see Figure 14)}$$




Figure 14. Test Gear Pitch Line Contact Stress (SK21984, SK21985, SI21988, and SK21989)

4. TEST RESULTS

Test Data

The objective of this experimental test program was to investigate candidate gear steels for increased surface load capacity, in comparison to the conventional (baseline) AISI 9310 gear steel.

A summary of the test results of this experimental program is shown in Tables 6 and 7 which contain the pertinent information obtained during the test phase, including part number, serial number, gear type, load levels, test cycles and failure mode.

The basic 100 percent design load level for this program was established as 2750 pounds per inch of face (3094 inch-pounds of torque) resulting in a bending stress of 38,513 psi and a contact stress at the pitch line of 179,800 psi.

The 100 percent design load was determined by using the current allowable pitch line contact stress of 150,000 psi for spur gears in existing Boeing-Vertol helicopter transmissions and applying a factor of 1.4 to account for the difference in operational characteristics of the Boeing-Vertol Gear Research Test Stand.

The basic load schedule for the baseline test gears SK21984 gear and SK21985 pinion (AISI 9310 steel) is presented in Table 4. The basic load schedule for the advanced gear material test gears SK21988 gear and SK21989 pinion (VASCO-X2, .24 carbon steel) is presented in Table 5.

The criteria for definition of a failure for all of the test gears used in this experimental program were established as follows: A minimum of one (1) pit per tooth, on each of three (3) non-adjacent teeth having a minimum dimension of 1/16-inch shall constitute a failure.

Discussion

Initial light scoring was observed at the 100 percent load level on most of the AISI 9310 gear test specimens. However, this condition appeared to stabilize and heal over at the conclusion of the 100 percent load run.

Initial light scoring is a state of lubrication phenomena which develops as a result of surface asperity contacts. The local

TABLE 4. LOAD SCHEDULE FOR BASELINE AISI 9310 STEEL GEARS

Run No.	Tangential Load, Wt (lb)	Pinion Torque (inlb)	Percent Load	Number of Test Cycles
1	687	1547	50	5.5 x 10 ⁴
2	1375	3094	100	3 x 106
3	2200	4950	160	3 x 106
4	2612	5879	190	3 x 10 ⁶

TABLE 5. LOAD SCHEDULE FOR VASCO-X2 STEEL GEARS

No.	Load, Wt (lb)	Torque (inlb)	Percent Load	Number of Test Cycles
1	687	1547	50	5.5×10^4
2	1375	3094	100	3×10^6
3	2612	5879	190	3×10^6
4	3025	6807	220	3 x 10 ⁶
5	3437	7735	250	3×10^6

A

SUMMARY OF TEST RESULTS FOR AISI 9310 STEEL TEST GEARS (SPUR) TABLE 6.

PART	SERIAL			LOAD LEVEL	BENDING STRESS	CONTACT	NUMBER OF	
NUMBER	NUMBER	NAME	SIDE	PERCENT	PSI	PSI	TEST CYCLES	RESULTS
SK21984	m	Gear	Ą	100	38,513	179.799	*	Rimonit
SK21985	ო	Pinion	Æ	160	61,621	227,428		Runout
				190	73,175	247,835		Pitting Failure -
								Pinion
SK21984	m	Gear	В	100	38,513	79,79	×	Runout
SK21985	м	Pinion	ф	160		4	1.3 × 106	Pitting Failure -
								Pinion
E SK21984	8	Gear	Ø	001	38 513	179 799	;	†*************************************
SK21985	1 0	Pinion	: A	160	61 621	207 700	< >	NullOut Birgint
	ļ	 	:	190	73,175	247, 420	י נ	Namour Ditting Failure
				•	ì		:	arning.
SK21984	2	Gear	М	100	38, 513	179 799	3 \$ 106	4::04::0
SK21985	0	Pinion	Ω	160	50,		; ;	; ;
	1		1)) 	4	r '	٠ •	ರ
SK21984	1	Gear	ď	100	38,513	179,799	3 × 106	Runout
SK21985	1	Pinion	ď	160	61,621	227,428		Pitting Failure -
SK21984	н	Gear	Д	100	38,513	_	×	Runout
SK21985	7	Pin:on	В	160	•	227,428	3 x 106	Pitting Failure -
								Pinion
SK21984	2	Gear	Ø	.100	38, 513	179,799	×	Runout
SK21985	Ŋ	Pinion	Ą	160	61,621	227,428	×	Runout
				190	73,175	247,835	3 x 106	Pitting Failure -

Pitting Failure - Pinion	1.97 x 106	227,428	61,621	160	p	FILLIOI	r	
	X M	79,7	38,513	100	m n	Gear	0 4	SK21984 SK21985
Pitting Failure - Pinion	1.3 x 106	227,428	61,621	160	ď	Pinion	4	SK21985
Runout	3 x 106	179,799	38,513	100	K	Gear	9 •	SK21984
Pitting Failure – Pinion	1.5 x 10°	V	70 1) }	1			
	m L	179,799	38,513 61 621	160	a m	Pinion	, rv	SK21985
Finion			i	0	р	<u>د</u> د و	и	SK2 1984
Pitting Failure -	×	247,835	73,175	190				
Runout	3 x 106	227,428	61,621	160	ď	Pinion	Ŋ	SK21985
Rinourt	*	179,799	38,513	.100	ď	Gear	2	SK21984
kunout Pitting Failure -	3 x 106	227,428	62	160	В	Pinion	1	SK21985
í	;	179 799	38, 513	100	В	Gear	1	SK21984
1 0	•							
Kunout Pitting Esiluro	1.5 × 106	227,428) IO	160	Ø	Pinion	7	SK21985
	;	7	38, 513	100	Ą	Gear	1	SK21984
1								
Pitting Failure -		42	52	160	Д	Pinion	7	SK21985
Riponit	3 × 106	179.799	38,513	100	М	Gear	7	SK21984
Pinion								
Pitting Failure -	6.2 ×	247,835	73,175	190				
Runout	m	227,428	61,621	160	Ą	Pinion	7	SK21985
Runout	3 ×	661.61T	516'96	DOT.	¢	-	1	1000

*The original pit on the pinion of approximately .20 inches occurred at 1.3 \times 10^6 cycles and this data was utilized in the statistical data.

TABLE 7. SUMMARY OF TEST RESULTS FOR VASCO-X2 STEEL TEST GEARS

PART NUMBER	SERIAL	NAME	SIDE	LOAD LEVEL PERCENT	BENDING STRESS PSI	CONTACT STRESS PSI	NUMBER OF	SEE TITODO
SK21988 SK21989	9 8	Gear Pinion	& &	100 190 220	38,513 73,175 84,729	179,799 247,835 266,678		2
SK21988 SK21989	11	Gear Pinion	αщ	100	-1 1- 0	179,799	* * * * * * * * * * * * * * * * * * *	_
sK21988 SK21989	0 0	Gear Pinion	44		38,513 73,175	179,799 247,835	× × ×	Pitting Failure - Pinion Runout
				220 250	84,729 96,283	266,678 284,280	3 x 106 5 x 105	runout Runout Pitting Failure - Pinion
SK21988 SK21989	0 0	Gear Piníon	αм	100 190 220 250	38,513 73,175 84,729 96,283	179,799 247,835 266,678 284,280	3 x 106 3 x 106 3 x 106 7.6 x 105	Runout Runout Ruting Failure - Pinion
SK21988 SK21989	m m	Gear Pinion	ፈ ፈ	100 190 220	38,513 73,175 84,729	179,799 247,835 266,678	3 x 106 3 x 106 1.3 x 106	Runout Runout Pitting Failure - Pinion
SK21988 SK21989	сε	Gear Pinion	дд	100 190 7 220 8	38,513 73,175 84,729	179,799 247,835 266,678	3 x 106 3 x 106 3 x 106	Runout Runout Pitting Failure -

THITCH								I
Ficting Fallure - Pinion	۲ ۲							
	ν (284,280	787	250				
Runout		247,835	ი ი	220)			
Kunout	×	2177177	ן ן ן ן	190	α	Pinion	2	SK21989
	;	179 799	513	100	B	Gear	S	SK21988
Pinion								
Pitting Failure -	×	\sim 1	8	250				
Runout	3 × 106	266,678	84,729	220				
Runout	×	m	73,175	190	¥	FINION	7	000000
Runout	×		38,513	700	¢	Dinion) L	SK21989
		Г	38 513	100	Ø	Gear	2	SK21988
Pitting Failure -			72	220				
Runout		247,835	,1	190	ф	Pinion	4	SN2 1989
אייסמויא	×	0	51	100	В	Gear	4	SK21988
Pinion								
Pitting Failure -	×	284,280	96,283	250				
Runout	×	266,678	72	220				
Runout		7	\vdash	190	ď	Pinion	4	5K21989
Rimont	×	179,799	51	100	4	Gear	4	SK2198
Pinion								
Pitting Failure -	×	266,678	, 72	220				
Runout	3 × 106	247,835		190	щ	Finion	n	606 1 2010
Runout	3×106	179,799	38,513	100	m 1	Gear n.	יי רי	SKZ1938
Pinion							,	
Pitting Failure -	1.3 x	66,67	72	220				
Runout	m	7,8	73,175	190	ď	Pinion	m	SK21989
Rimonit	m	179,799	51	100	Ø	Gear	m (SK21988
	7.6	284,28	96,283	250				
	i X	266,	84,729	220				
	m	247,83	73,175	190	щ	Pinion	.7	SKZ 1989
Ringiit	χ m	179,79	38,513	100	Д	Gear	0 0	SK2 1988
FINION							1	
Pinion								


high spots concentrate the load in these areas permitting metalto-metal contact, along with concentrated pressures. Continued operation at moderate loads will eventually wear down the localized high spots (asperities) and thereby permit improved load distribution which in turn will result in a healed over (polished) condition.

The frosting condition on the pinion dedendum was usually observed at the 160 percent load level; however, the severity of this condition was not apparent to normal observation. The final condition of the AISI 9310 gear test specimens, which displayed the typical pitting and/or spalling condition is presented in Figures 15 through 19. These figures also show the typical frosting condition identified by the etch-like appearance of the surface on the pinion dedendum. Under magnification, the frosted surface appears to contain a field of micro-pits with no evidence of radial welding and/or tear marks.


The test program for the VASCO-X2 gear test specimens was completed with little or no evidence of scoring except for the last test set, SK21989, Serial No. 5. At the 190 percent load level for this set, a significant change in the vibration signature was observed and the test was interrupted. Subsequent removal and inspection of the gears, bearings, and shafting revealed that the inner race bearing spacer had excessive longitudinal play. The test pinion sustained medium scoring from the first point of contact to a point above pitch line. The gear member sustained medium scoring from the outside diameter to a point below the pitch line. The bearing spacer condition was corrected and the test program continued.

In most cases, a frosting condition was observed during the 190 percent load run. This condition appeared to taper across the face width with the widest portion located at the end closest to the mounting shoulder. The final condition of the VASCO-X2 gear test specimens displaying the typical pitting and/or spalling condition is presented in Figures 20 through 23. These same figures show the typical frosting condition, identified by the etch-like appearance of the surface, on the pinion dedendum. They also show the highly polished condition of the remaining tooth surface, with no evidence of scoring. Under magnification, the frosted surface appears to contain a field of micro-pits with no evidence of radial welding and/or tear marks.

The pitting condition sustained by the gear test specimens for both materials under investigation appear to be typical of destructive pitting usually found in the dedendum of the driving member in a reduction gear drive. This condition is characterized by the appearance of large pits, in excess of 1/32-inch in diameter in the dedendum region. This type of pitting failure will usually progress in size and number of pits, with repeated stress cycles, and can eventually lead to catastrophic failure. Assuming that the material integrity is sound, and that




SIDE A, TOOTH 2, 190 PERCENT LOAD, 6.2 X 10^5 CYCLES




SIDE B, TOOTH 21, 160 PERCENT LOAD, 2.3 X 106 CYCLES

Figure 15. Final Condition of AISI 9310 Steel Test Pinion (SK21985, Serial No. 2).




SIDE A, TOOTH 16, 190 PERCENT LOAD, 3.0 X 106 CYCLES



SIDE B, TOOTH 22, 160 PERCENT LOAD, 1.3 X 106 CYCLES

Figure 16. Final Condition of AISI 9310 Steel Test Pinion (SK21985, Serial No. 3).




SIDE A, TOOTH 4, 190 PERCENT LOAD, 3.0 \times 10⁶ CYCLES




SIDE B, TOOTH 4, 160 PERCENT LOAD, 1.5 X 106 CYCLES

Figure 17. Final Condition of AISI 9310 Steel Test Pinion (SK21985, Serial No. 5).




SIDE A, TOOTH 8, 160 PERCENT LOAD, 1.3 X 106 CYCLES




SIDE B, TOOTH 23, 160 PERCENT LOAD, 1.97 X 10^6 CYCLES

Figure 18. Final Condition of AISI 9310 Steel Test Pinion (SK21985, Serial No. 4).




SIDE A, TOOTH 1, 160 PERCENT LOAD, 1.5 \times 10⁶ CYCLES




SIDE B, TOOTH 2, 160 PERCENT LOAD, 3.0 X 106 CYCLES

Figure 19. Final Condition of AISI 9310 Steel Test Pinion (SK21985, Serial No. 1).




SIDE \hat{A} , TOOTH 16, 250 PERCENT LOAD, 9.8 X 10⁵ CYCLES




SIDE B, TOOTH 17, 220 PERCENT LOAD, 3 X 106 CYCLES

Figure 20. Final Condition of VASCO-X2 Steel Test Pinion (SK21985, Serial No. 4).




SIDE A, TOOTH 11, 220 PERCENT LOAD, 1.3 \times 10⁶ CYCLES




SIDE B, TOOTH 14, 220 PERCENT LOAD, 3 \times 10⁶ CYCLES

Figure 21. Final Condition of VASCO-X2 Steel Test Pinion (SK21989, Serial No. 3).




SIDE A, TOOTH 8, 250 PERCENT LOAD, 5 X 10⁵ CYCLES




SIDE B, TOOTH 13, 250 PERCENT LOAD, 7.6 X 106 CYCLES

Figure 22. Final Condition of VASCO-X2 Steel Test Pinion (SK21989, Serial No. 2).



SIDE A, TOOTH 16, 250 PERCENT LOAD, 3.9 X 105 CYCLES



SIDE B, TOOTH 13, 250 PERCENT LOAD, 1.4 \times 10⁶ CYCLES

Figure 23. Final Condition of VASCO-X2 Steel Test Pinion (SK21989, Serial No. 5).

fabrication process specifications are successfully completed, this type of failure usually indicates that the operating load sustained at the time of failure is in excess of the material surface endurance limit.

All of the gear test specimens (AISI 9310 and VASCO-X.) were inspected by the nital etch process after completion of the test program. This inspection revealed a contact burn condition in the pinion dedendum on all of the AISI 9310 steel test pinions. This condition is usually indicative of high temperature and/or concentrated pressure. A micro examination is presented in Figure 24. The photograph displays the burned area, located approximately 0.012 inch above the fillet radius juncture, 0.064-inch in length, and 0.0025-inch deep. This condition was not evident on the VASCO-X2 steel test pinions.

Data Analysis

Test data evaluation was accomplished using statistical methods to establish reliable surface contact stress endurance value limits for the two materials under investigation. The life factor C in AGMA Standard 210.02, "Surface Durability (Pitting) of Spur Gear Teeth", was used to project the contact stress endurance limit to 10 million cycles for the test data points. Figure 25 represents the surface durability life factor which was employed for projection of the test data.

All of the test data points, for both materials, listed in Tables 6 and 7 were projected for the expected endurance limit at 10 million cycles. As shown in Figure 25, the life factor C_L becomes unity at 10 million cycles, indicating that the surface fatigue endurance limit is achieved at that point. The number of test cycles to failure for each data point was used to determine the correct life factor for application to each data point. This life factor was then employed to determine the calculated endurance limit at 10 million cycles by dividing the contact stress at failure, for each data point, by the respective life factor. A listing of the specific data points, life correction factors, and calculated endurance limits is presented in Table 9.

An existing Boeing-Vertol computer program was used for the statistical data evaluation. This study was accomplished by employing the following method of analysis. The various calculated surface endurance stress indices were used to determine the mean (50 percent failure rate) endurance stress, the unbiased standard deviation, and the 99 percent confidence limits for the mean endurance limit. Figure 26 presents a plot of the test data points with the mean endurance limit and the associated 99 percent confidence limits. The plotted data presented in Figure 26 is also listed in tabular form in Table 8.




Figure 24. Contact Burn on AISI 9310 Steel Pinion (Scale 25x)

TABLE 8. RESULTS OF STATISTICAL ANALYSIS

Material	Number of Data Points Anelyzed	Mean (50% Failure) Endurance Limit at 10 ⁷ Cycles (stress, psi)	Lower Limit on Mean (99% Confidence) (stress, psi)	Unbrased Standard Deviation (stress, psi)	Unbiased Standard Deviation at 99.5% Probability (stress, psi)	Stress at 99.5% Probability of Survival (psi)
VASCO-X2 (.24 Carbon- CVM)	10	241,800	235,200	6,400	23,700	211,500
AISI 9310 (AMS 6260)	10	209,000	199,500	9,200	34,100	165,400

TABLE 9. TEST DATA AND CALCULATED ENDURANCE LIMITS

-	Stress at		AGMA Standard	
	Failure	Cycles at	210.02	Calculated Endurance
	(psi)	Failure	Life Factor, CL	Limit at 10 ⁷ Cycles (stress, psi)
				(octobs, psi)
			VASCO-X2	
	284,290	1,430,000	1.127	252,250
	284,290	980,000	1.1505	247,100
	284,290	760,000	1.168	243,400
	284,290	500,000	1.1945	238,000
	284,290	390,000	1.2105	234,850
	266,690 266,690	3,000,000	1.078	247,390
	266,690	3,000,000	1.078	247,390
	266,690	1,420,000 1,300,000	1.128	236,430
	266,690	1,300,000	1.132	235,590
	200,000	1,300,000	1.132	235,590
			AISI 9310	
	247,840	3,000,000	1.078	229,910
	247,840	1,300,000	1.132	218,940
	247,840	620,000	1.181	209,860
	227,430	3,000,000	1.078	210,970
	227,430	2,300,000	1.095	207,700
	227,430	1,970,000	1.105	205,820
	227,430 227,430	1,500,000	1.123	202,520
	227,430	1,500,000	1.123	202,520
	227,430	1,300,000 1,300,000	1.132	200,910
	//430	±,300,000	1.132	200,910




Figure 25. Surface Durability Life Factor (AGMA Standard 219.02)





Figure 26 Mean Endurance Limits for a 99.5 Percent Probability of Survival.

The data was further evaluated by assuming the lower limit of the mean as the actual mean, which results in an endurance limit with a 99 percent confidence and a 50 percent probability of survival. The mean endurance limit for a 99.5 percent probability of survival was then calculated using student's t distribution factors, which resulted in the data presented in Figure 27. With these results, a comparison of the two materials can be accomplished at a 99.99 percent probability of survival (standard aircraft gear design practice) with a confidence level of 99 percent.

Analysis of the comparison of the two materials indicates that the mean (50 percent failure rate) endurance limit of the VASCO-X2 steel is approximately 15.7 percent higher than the mean endurance limit of the AISI 9310 steel. However, application of the 99.99 percent probability of survival level with a 99 percent confidence which is normally associated with aircraft design design practice increases this improvement for the VASCO-X2 steel to approximately 33.8 percent.



Test Data Points with Mean Endurance Limits at 99 Percent Confidence Level 27 Figure

5. CONCLUSIONS

- On the basis of the test results obtained from this experimental test program, the VASCO-X2 (.24 carbon) steel test gears achieved load levels of 30 to 60 percent higher than the baseline AISI 9310 (AMS6260) steel test gears.
- 2. The statistical evaluation of the test results, using typical aircraft confidence and survival levels, indicates an improvement in the design endurance limit for the VASCO-X2 gear specimens of approximately 34 percent.
- 3. Present design philosophy assumes that there is not substantial difference in allowable contact stress for gear steels of the same quality. The results of this test program indicate that this contention is not necessarily applicable to advanced gear steels.
- 4. Metallurgical examination of the AISI 9310 gear specimens revealed a contact burn in the pinion dedendum, indicating that excessive temperatures were present. The VASCO-X2 test gear specimen did not exhibit this condition. Since the test gear design and operating condition were the same for the VASCO-2 gears, it is reasonable to assume that the high hot hardness VASCO-X2 steel gears can withstand higher operating temperatures and/or concentrated pressures than the AISI 9310 steel gears.
- The percentage of retained austenite and degree of carbide network in the VASCO-X2 steel test gears, disclosed by the metallurgical examination, are above the levels normally associated with low alloy steels such as, AISI 9310. Evaluation of the effect of these conditions, on the load carrying capacity of the VASCO-X2 steel test gears, is uncertain at this time since no quantitive controls have ever been established for the microstructure of this material. However, from the chemistry of this material, it seems reasonable to expect a heavier carbide network since carbide formers such as; molybdenum, tungsten, and chromium are present to a greater degree in this material compared to the low alloy steels. The slight variations in chemistry from the basic percentages were negligible and had little or no effect on the load carrying characteristics of the VASCO-X2 steel gears.

6. RECOMMENDATIONS

Based on the results obtained from the experimental testing and evaluation performed during the execution of this program, it is recommended that further work be directed to the following areas.

- Conduct an experimental test program to determine the capability of operation at higher oil-in temperatures (250°F to 300°F) for the VASCO-X2 material as compared to the current gear steels.
- 2. Establish a reliable production type heat treat and carburizing specification for VASCO-X2 tool steel to ensure compliance with design specifications and repeatability of manufacture.
- Fabricate VASCO-X2 steel test specimens using the production type heat-treat and carburizing specification; and conduct single-tooth bending tests for comparison with the previous results from contract number N00156-69-C-0634 (Reference 2).

7. REFERENCES AND BIBLIOGRAPHY

REFERENCES

- 1. Albrecht, C., Statistical Evaluation of a Limited Number of Fatigue Test Specimens Including a Factor of Safety Approach, Fourth Pacific Area National Meeting of the American Society for Testing and Materials, Los Angeles, California (October 1-5, 1963).
- 2. Lemanski, A. J. Alberti, J. P. and H. J. Rose, <u>Evaluation of Advanced Gear Materials for Gear Boxes and Transmissions</u>, <u>Engineering Final Report (Item 1) Contract N00156-69-C-0634</u>
 Department of the Navy Naval Air Propulsion Test Center Philadelphia, Penna., August 1969.

BIBLIOGRAPHY

Arley, N. and K. R. Buch, <u>Introduction to the Theory of Probability and Statistics</u>, John Wiley & Sons, Inc., New York (1950).

Fatigue, Committee on E-9, Fatigue Testing and the Statistical Analysis of Fatigue Data, ASTM Manual on Fatigue Testing, STP Number 91.

Hoel, P. G., Elementary Statistics, John Wiley & Sons, Inc., New York (1960).

Mack, J. C. and B. D'Angelo, <u>Evaluation of the Effect of Gear Tooth Grinding Methods on Fatigue Life of Spur Gears</u>. Boeing Company, Vertol Division Technical Report Number R342-A (1964).

McIntire, W. L. and R. C. Malott, <u>Advancement of Spur Gear Design Technology</u>, Contract DA44-177-AMC-318(T), U. S. Army Aviation Materiel Laboratories, Fort Eustis, Virginia (1966).

Rating the Strength of Spur Gear Teeth, American Gear Manufacturers Association Standard 220.02.

Seabrook, J. B. and D. W. Dudley, Results of a Fifteen Year Program of Flexural Fatigue Testing of Gear Teeth. ASME Document Number 63-WA-199.

Surface Durability of Spur Gears, American Gear Manufacturers Association Standard 210.02.

Weibull, W., Fatigue Testing and Analysis of Results, The Macmillan Company, New York (1961).

Security Classification

DOCUMENT COL (Security classification of title, body of abstract and indexis	NTROL DATA - R&	D	he overall second to classified)		
1. ORIGINATING ACTIVITY (Corporate author)			RT SECURITY CLASSIFICATION		
The Boeing Company, Vertol Divi	sion		nclassified		
Boeing Center, P.O. Box 16858 Philadelphia, Pennsylvania 19	142	26 GROUP			
3. REPORT TITLE					
Evaluation of Advanced Gear Mat	erials for				
Gear Boxes and Transmissions					
4. DESCRIPTIVE NOTES (Type of report and inclusive dates)	-				
Final (August 1968 to October 1	970)				
5. AUTHOR(\$) (Lost name, first name, initial)					
Albert, J.P.: Lemanski, A. J.					
6. REPORT DATE	74- TOTAL NC. OF F	24658	76 NO. OF REFS		
October 1970	/ TOTAL IC. O	A46.3	2		
SE CONTRACT OR GRANT NO.	94. ORIGINATOR'S R	EPORT NUM	BER(S)		
N00156-69-C-0634	D210-101				
b. PROJECT NO.					
c.	9b. OTHER REPORT	NO(S) (Any	other numbers that may be easigned		
d.					
10 AVAILABILITY/LIMITATION NOTICES					
This document is subject to spec					
mission to foreign governments or foreign nationals may be made					
only with prior approval of Naval Air Systems Command (AIR 536B2)					
11. SUPPLEMENTARY NOTES	12. SPONSORING MILI	TARY ACTIV	ΛΙΤ̈́Υ		
	Naval Air	System	ms Command		
, V	Departmen	nt of the	ne Navy		
	Washingto	n, D.C	•		
13 ABSTRACT					
Helicopter transmission gear ma-	terials are	select	ed mainly for their		
strength. Sliding behavior is					
surfaces of the gears. However					
limit the performance of the tra	ansmission,	under d	conditions which		
are not severe enough to cause	tooth breaka	ige. li	n the search for		
		_			

Helicopter transmission gear materials are selected mainly for their strength. Sliding behavior is normally improved by hardening the surfaces of the gears. However, pitting and spalling may occur to limit the performance of the transmission, under conditions which are not severe enough to cause tooth breakage. In the search for more reliable gear materials, the VASCO-X2 high hot hardness tool steel had previously demonstrated the capability of carrying 2.40 times the design load for 10 million cycles without evidence of pitting or spalling. Further, there was evidence that the VASCO-X2 test gears developed a protective surface layer on the working tooth under operating loads. The current test program consisted of rotating load/tests on gear specimens with a tooth geometry designed to achieve pitting and spalling. VASCO-X2 (.24 carbon) high hot hardness tool steel gears, when tested against baseline gears of AISI 9310 (AMS 6260) aircraft gear steel, demonstrated a 30-percent greater load carrying capability. A protective surface layer appeared to form on the VASCO-X2 gears lowering critical temperatures during operation.

DD . JAN. 1473

Unclassified

Security Classification

KEY WORDS	LIN	KA	LINI	(8	LIN	K C
	ROLE	WT	ROLE	wT	ROLE	W
Advanced Gear Materials						
AISI 9310 Steel						
Gear Boxes and Transmissions						
Pitting Failure						
Spalling Failure						
Surface Fatigue						
VASCO-X2 Steel						
			İ			

INSTRUCTIONS

- 1. ORIGINATING ACTIVITY: Enter the name and address of the contractor, subcontractor, grantee, Department of Defense activity or other organization (corporate author) issuing the report.
- 2a. REPORT SECURITY CLASSIFICATION: Enter the overall security classification of the report. Indicate whether "Restricted Data" is included. Marking is to be in accordance with appropriate security regulations.
- 2b. GROUP: Automatic downgrading is specified in DoD Directive 5200. 10 and Armed Forces Industrial Manual. Enter the group number. Also, when applicable, show that optional markings have been used for Group 3 and Group 4 as authorized.
- 3. REPORT TITLE: Enter the complete report title in all capital letters. Titles in all cases should be unclassified. If a meaningful title cannot be selected without classification, show title classification in all capitals in parenthesis immediately following the title.
- 4. DESCRIPTIVE NOTES: If appropriate, enter the type of report, e.g., interim, progress, summary, annual, or final. Give the inclusive dates when a specific reporting period is covered.
- 5. AUTHOR(S): Enter the name(s) of author(s) as shown on or in the report. Enter last name, first name, middle initial. If military, show rank and branch of service. The name of the principal author is an absolute minimum requirement.
- 6. REPORT DATE: Enter the date of the report as day, month, year, or month, year. If more than one date appears on the report, use date of publication.
- 7a. TOTAL NUMBER OF PAGES: The total page count should follow normal pagination procedures, i.e., enter the number of pages containing information.
- 7b. NUMBER OF REFERENCES: Enter the total number of references cited in the report.
- 8a. CONTRACT OR GRANT NUMBER: If appropriate, enter the applicable number of the contract or grant under which the report was written.
- 8b, 8c, & 8d. PROJECT NUMBER: Enter the appropriate military department identification, such as project number, subproject number, system numbers, task number, etc.
- 9a. ORIGINATOR'S REPORT NUMBER(S): Enter the official report number by which the document will be identified and controlled by the originating activity. This number must be unique to this report.
- 9b. OTHER REPORT NUMBER(S): If the report has been assigned any other report numbers (either by the originator or by the sponsor), also enter this number(s).
- 10. AVAILABILITY/LIMITATION NOTICES: Enter any limitations on further dissemination of the report, other than those

imposed by security classification, using standard statements such as:

- (1) "Qualified requesters may obtain copies of this report from DDC."
- (2) "Foreign announcement and dissemination of this report by DDC is not authorized."
- (3) "U. S. Government agencies may obtain copies of this report directly from DDC. Other qualified DDC users shall request through
- (4) "U. S. military agencies may obtain copies of this report directly from DDC. Other qualified users shall request through
- (5) "All distribution of this report is controlled. Qualified DDC users shall request through

If the report has been furnished to the Office of Technical Services, Department of Commerce, for sale to the public, indicate this fact and enter the price, if known

- 11. SUPPLEMENTARY NOTES: Use for additional explanatory notes.
- 12. SPONSU: ING MILITARY ACTIVITY: Enter the name of the departmental project office or laboratory sponsoring (paying for) the research and development. Include address.
- 13. ABSTRACT: Enter an abstract giving a brief and factual summary of the document indicative of the report, even though it may also appear elsewhere in the body of the technical report. If additional space is required, a continuation sheet shall be attached.

It is highly desirable that the abstract of classified reports be unclassified. Each paragraph of the abstract shall end with an indication of the military security classification of the information in the paragraph, represented as (TS), (S), (C), or (U).

There is no limitation on the length of the abstract. However, the suggested length is from 150 to 225 words.

14. KEY WORDS: Key words are technically meaningful terms or short phrases that characterize a report and may be used as index entries for cataloging the report. Key words must be selected so that no security classification is required. Identifiers, such as equipment model designation, trade name, military project code name, geographic location, may be used as key words but will be followed by an indication of technical context. The assignment of links, rules, and weights is optional.

Unclassified